




FIG. 2  
PRIOR ART










FIG. 5




FIG. 6




FIG. 7

310




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14A

FIG. 14

FIG. 14A

FIG. 14B




FIG. 14B




FIG. 15

100 ↗




FIG. 16

REPLACEMENT SHEET

18/32




FIG. 17




FIG. 18




FIG. 19

REPLACEMENT SHEET

21/32

HARD HANDOFF FROM LEGACY IS41 MSC TO 802.11 MSC




FIG. 20




FIG. 21

REPLACEMENT SHEET

23/32




FIG. 22




FIG. 23




FIG. 24




FIG. 25






FIG. 26

**FIG. 27**

**FIG. 28**




FIG. 29




FIG. 30




FIG. 31